

# CASE STUDY: EMERGENCY RESPONSE

## Project Summary-

To make safe and remove unsafe steel structure from the top of a retail outlet store in a sensitive town centre position

Actions taken:

Clearance of emergency with regulatory bodies.

Rapid response to Client's requirements.

Rapid assessment of risks and potential impact on Client and development of documented method statements.

Adoption of coordinated lift and cut regimes to safely remove unstable structure.

Coordination of plant isolation and definition of work areas to minimise disruption to Client.

Close liaison with all site personnel.

Clearance of debris from site to leave safe as per Client's requirements.



**BDB Dismantling Limited**

**Valley Road, Station Road Industrial Estate, Wombwell, Barnsley, S73 0BS**

**Phone: 01226 273860 Fax: 01226 754180 E-mail: [marketing@bdbdismantling.co.uk](mailto:marketing@bdbdismantling.co.uk)**